

---

Subject: K100 2 Questions

Posted by [Dutleydurite](#) on Wed, 11 Mar 2020 01:49:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello all! I have replaced several of the input transistors with 2N3904 transistors. I have some volume, not just the faint signal I started with. I had to carefully dial the volume to around 10 o'clock at the start. The amp sounds farty and has little volume even when turned all the way up. Amp hissing is pretty significant at peak volume. I don't read schematics well. It's a pc104 board. I'm needing some help as I don't have somewhere to take it to. Thanks in advance.

---