Subject: K100-1
Posted by Breakersbass on Sat, 08 Oct 2016 00:10:26 GMT
View Forum Message <> Reply to Message

Found 200 nohm resistor culprit.