Subject: Dead K 100 Piggyback
Posted by Breakersbass on Fri, 07 Oct 2016 21:04:38 GMT
View Forum Message <> Reply to Message

I was given a beautiful Blue K100 piggyback last week.When I got it home I found at some point roaches had decided to hang out.The amp is dead. Once I cleaned all the bugs I started to look into the issue.I have about 38 volts on both pilot lamp leads and I found where someone had replaced a SE 4002 (located and the bottom of the board on the right side) with a 2s transistor.I replaced it with the suitable sub for the se 4002.Any thoughts on where I should look .Any help will be appreciated.