Subject: Re: Kustom 100 blowing fuse Posted by timetraveler on Tue, 04 Jun 2019 17:31:08 GMT View Forum Message <> Reply to Message

theres two capacitors with a red dot is that the positive side? there one with a white dot as well is that the negative side?

Page 1 of 1 ---- Generated from VintageKustom.com