
Subject: K-100 SC 4X10" speakers

Posted by chopr1@aol.com on Fri, 29 Jun 2018 02:54:16 GMT

[View Forum Message](#) <> [Reply to Message](#)

The reverb tank in my amp has a broken transducer. I want to replace the tank with a new one. I have read MANY opinions on which one to use. Would like to know which one is recommended to swap it out. Ohm readings on the cables are 177 and 182 ohms. I have other tanks on other amps I have replaced and the ohm reading on those are totally different than this one. Example 1450 and 2240 ohms. I can not find any replacements with the 177-182 ohm options. What am I missing. Thanks for any help.
