
Subject: Re: K150-6 pumps out DC voltage when powered on.
Posted by [steven](#) on Mon, 16 Mar 2020 10:06:24 GMT
[View Forum Message](#) <> [Reply to Message](#)

That small amount of D.C. Is normal.

Now get some top hat type slip on heat sinks for those Transistors.
