Subject: Filter caps - K100-2

Posted by gui\_tarzan on Wed, 03 Jun 2015 21:06:46 GMT

View Forum Message <> Reply to Message

So the stock caps are 2500mfd, 50v and I have some 2200/50v but they're TINY compared to the originals. I know, they're large cans vs small radials, I'm just unsure if they're big enough physically or if it even makes a difference?

Subject: Re: Filter caps - K100-2

Posted by chicagobill on Wed, 03 Jun 2015 22:15:49 GMT

View Forum Message <> Reply to Message

Size doesn't matter. Well at least physical size doesn't.

The original Mallory caps were called "computer grade", which meant that they were designed to a higher standard than normal consumer grade caps. That is part of the reason that they have lasted so long.

Modern caps are much smaller than old caps, but the trade off is that they don't seem to last as long.

In the rare occasions that I need to replace them, I use the larger sized "snap-in" caps, which come in larger diameters. I will either build a small circuit board to hold the new caps in place that has screw in contact points to connect the original wires to or I use some sort of thick ring to adapt the smaller diameter caps to the size of the original cap clamps.

Some folks like to increase the value of the caps to double or triple the original ratings.

Subject: Re: Filter caps - K100-2

Posted by Kustom Bart on Thu, 04 Jun 2015 19:26:22 GMT

View Forum Message <> Reply to Message

For sure what ChicagoBill said, do not go lesser value of modern caps, go bigger and they will last much much longer. That is exactly what my guy told me to do that fixes the stuff on mine that I can't.

Subject: Re: Filter caps - K100-2

Posted by qui tarzan on Thu, 04 Jun 2015 22:11:05 GMT

View Forum Message <> Reply to Message

That's what I thought, I haven't worked on one of these before so I wanted to be sure. Thanks!

Subject: Re: Filter caps - K100-2

Posted by gui\_tarzan on Fri, 05 Jun 2015 01:58:44 GMT

View Forum Message <> Reply to Message

Fortunately I didn't have to get into the caps, I cleaned the jacks and pots and the raucous hum went away so my guess is one of the input jacks wasn't shorting correctly.

Subject: Re: Filter caps - K100-2

Posted by stevem on Fri, 05 Jun 2015 10:24:55 GMT

View Forum Message <> Reply to Message

That would be correct and a cool easy fix, no?

Subject: Re: Filter caps - K100-2

Posted by gui tarzan on Fri, 05 Jun 2015 12:09:19 GMT

View Forum Message <> Reply to Message

Yep! The original question was more for information, I haven't seen caps like that in a SS amp before.

Subject: Re: Filter caps - K100-2

Posted by stevem on Fri, 05 Jun 2015 12:18:32 GMT

View Forum Message <> Reply to Message

To this day I am still no sure that the original big can type filters do not make for less power supply sag at high output levels as compared to new smaller ones!