

---

Subject: K100-1

Posted by [Breakersbass](#) on Sat, 08 Oct 2016 00:10:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Found 200 nohm resistor culprit.

---