Subject: Kustom 50-2 Amp Ground Cord

Posted by jammy5152 on Tue, 19 Apr 2022 01:49:04 GMT

View Forum Message <> Reply to Message

Hey

I have replace the 2 prong power cord with a 3 prong power cord and noticed a cap that reads 0.22 uF/ 150 VAC

which is soldered to the middle leg of the switch with 1 lead and the other lead is grounded to a screw post on the back of the amp....

I'm using that ground post for my green wire now was wondering is that the " Death Cap" and should it be cut

out of the switch area...??

I have not turned it on yet while waiting for another part ...

This is a Kustom 50-2 amplifier...

Thanks

Subject: Re: Kustom 50-2 Amp Ground Cord Posted by stevem on Tue, 19 Apr 2022 10:10:06 GMT

View Forum Message <> Reply to Message

Just cut it out completely.

Is this the amp you need the volume intensity pot for?

Subject: Re: Kustom 50-2 Amp Ground Cord

Posted by jammy5152 on Tue, 19 Apr 2022 11:22:51 GMT

View Forum Message <> Reply to Message

Yes it is ... It's for the Vib/ Tremelo though...I have a pot coming in which I might be able to remove the shaft to replace in mine...

Subject: Re: Kustom 50-2 Amp Ground Cord

Posted by stevem on Tue, 19 Apr 2022 14:16:37 GMT

View Forum Message <> Reply to Message

What is bad with your original pot/swt?

Subject: Re: Kustom 50-2 Amp Ground Cord

Posted by jammy5152 on Wed, 20 Apr 2022 00:46:49 GMT

View Forum Message <> Reply to Message

stevem

The shaft is broken on the pot...I took it apart and the shaft is missing completely and the rear of the pot is in broken plastic pieces ...This must have fallen over sometime ago (I got it from someone) I'm waiting on a pot that looks just like it and will replace the front of the pot with the shaft

Thanks