
Subject: Help needed to troubleshoot Kustom PA 200 Channels

Posted by [bproctor](#) on Mon, 17 Oct 2016 23:35:16 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi Everyone.

I am finally getting around to fixing my Kustom 200 PA Head. Channels 2 and 4 are dead. I blew out the dust and applied deoxit to the pots. How do i check capacitors and or transistors. Sound appears to be OK from the other channels.

Thanks,

Brian

Subject: Re: Help needed to troubleshoot Kustom PA 200 Channels

Posted by [stevem](#) on Tue, 18 Oct 2016 10:15:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

Can you solder, do you have a tube type solder sucker, can you read a schematic and do you have a volt / ohm meter and know how to test transistors?

Subject: Re: Help needed to troubleshoot Kustom PA 200 Channels

Posted by [stevem](#) on Wed, 19 Oct 2016 10:00:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

Even if you can just solder and unsoldering cleanly, changing out the first gain stage transistor will likely get both channels up and running, and the transistors these days are so cheap that it's fine to just shot gun the preamp boards and not even test the transistors you yank out!

Subject: Re: Help needed to troubleshoot Kustom PA 200 Channels

Posted by [bproctor](#) on Wed, 19 Oct 2016 12:28:46 GMT

[View Forum Message](#) <> [Reply to Message](#)

Thanks for the help.

I am OK at soldering, and have a multi-meter.

My neighbor is a whiz at electronics repair, and I will probably have him to the surgery.

I am just looking to do the leg work so that he has the information he needs (schematics, usual suspects, etc).

As far as the gain stage transistor is concerned, is there one of these per channel? This would be the first transistor after input.

Looks like the schematic links are down. I will try to print this out when it becomes available.

Thanks again

Subject: Re: Help needed to troubleshoot Kustom PA 200 Channels
Posted by [steven](#) on Wed, 19 Oct 2016 13:17:16 GMT

[View Forum Message](#) <> [Reply to Message](#)

The schematic section of this site is working fine, as I just tried it.
You need to have your tech friend look at the PC105 schematic and change out transistor Q100 next to the boards volume pot .

Subject: Re: Help needed to troubleshoot Kustom PA 200 Channels
Posted by [chicagobill](#) on Wed, 19 Oct 2016 16:10:56 GMT

[View Forum Message](#) <> [Reply to Message](#)

If your friend is a whiz, then he should first be able to test the transistors to see if that is the problem.

Subject: Re: Help needed to troubleshoot Kustom PA 200 Channels
Posted by [bproctor](#) on Wed, 19 Oct 2016 20:23:34 GMT

[View Forum Message](#) <> [Reply to Message](#)

Great info. I will have him check it out and report back.
He mainly works on classic arcade video games, but this shouldn't be too much of a stretch
Thanks,
Brian
