

---

Subject: Thermal Sensor K-150-6

Posted by [navigio](#) on Wed, 08 Jul 2009 00:31:42 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello there: 1st post and hope it is getting out correctly.

Have a DOA Elmwood Sensor 2455 on this combo K-150-6 serial 81628. Shop tech has substituted a sensor from another application for brief test. It powers up previously dead amp, plays fine. Can anyone give me the schematic values for this sensor (better yet, schematic!) or recommend a replacement part (maker & number) and source? It is round with two spade connectors; screws down with retainer ring. I'm not a tech so I apologize in advance if I've left out info you need. Flying blind, you see. Your assist is much appreciated. Thanks, in advance.

---