Subject: Kustom 100 blowing fuse Posted by imsteinrecording on Tue, 08 Jan 2013 10:45:17 GMT View Forum Message <> Reply to Message

Hi,

I'm new to the group also. I have a similar problem to the other user who has an amp blowing fuses. Mine is a Kustom 100, model K100 2. It blows fuses immediately. I read the other threads and was wondering if the possible fixes are the same, ie. a driver or output transistor. I'm not sure what a driver is! Thank you in advance and Happy New Year!

Sincerely,

Mark

