
Subject: K200B head

Posted by [Bob's Guitars](#) on Wed, 18 Apr 2018 21:08:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

Not very loud but it's there. Also the noise floor varies. Is this the sound of preamp xsistors dying?
Thanks, JT
