
Subject: Kustom 250-4

Posted by [johnnysynth](#) on Thu, 09 Jan 2020 17:23:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

I'm rebuilding a Kustom 250-4 amp. It works but is noisy and distorts in the high end frequencies with my Wurlitzer Electric Piano. Right now rebuilding the (2) preamp sections starting with the 14pin dual op-amps XR4739/nte725 uA739

This part is not listed in Mouser or Digikey

Any clues on this or any other -hard to find- devices in the pre-amp section?

I replaced the two 'big can' electrolytics already in the pwr. supply and that brought the idyl noise down considerable

That's as far as I've gotten

Jake Welsh

johnnysynth@yahoo.com

808 755-5886

Saint Augustine, FL

1/9/20
