
Subject: K100c-7 intermittent signal
Posted by [natedriver](#) on Sat, 30 Sep 2017 20:41:07 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hi I have a k100c-7 slant face amp and it randomly stops outputing signal. almost everytime this has occured the amp is on and resting an it hen just stops hissing. indicator light is on i turn off then on and no thump. wait a while and then it pops back on.

i do slam some pedals into it but it usaully cuts out when nothing is being played. it has a pretty big thump. Fllter caps gone bad?

Thanks Nate

Subject: Re: K100c-7 intermittent signal
Posted by [pleat](#) on Sun, 01 Oct 2017 00:17:20 GMT
[View Forum Message](#) <> [Reply to Message](#)

I had the same amp and issue. I found that the CR902 diode on the power amp board had slipped out of it's clip. the diode snaps into a retaining clip on the frame that the power transistors are mounted on. Once the amp cooled down a bit, the amp would work, then fade out. Clipped the diode into it's mounting clip and has ran ever since without fail.

Just a thought.
pleat

Subject: Re: K100c-7 intermittent signal
Posted by [chicagobill](#) on Sun, 01 Oct 2017 04:52:47 GMT
[View Forum Message](#) <> [Reply to Message](#)

If the amp pilot lamps stay lit and it's just the sound that dies out, then I'd check the speaker and the wiring for loose connections or broken solder joints.

Subject: Re: K100c-7 intermittent signal
Posted by [steven](#) on Sun, 01 Oct 2017 10:13:56 GMT
[View Forum Message](#) <> [Reply to Message](#)

If both channels are cutting out and you have another amp around take the signal out of the amps monitor jack, if that signal cuts out too when the Kustom craps out then you have a issue on the PC 900 driver/ power amp board.

My first guess on this issue would be a bad solder connection, or that first input Transistor (Q900) is going intermittent.

Also make sure the Blue wire that feeds the speaker output jack has good connections ar both

ends.

Hopefully it will be a easy fix like what Bill told you to check, let us know what you find.

Subject: Re: K100c-7 intermittent signal
Posted by [natedriver](#) on Sun, 01 Oct 2017 17:27:53 GMT
[View Forum Message](#) <> [Reply to Message](#)

im wondering if im overloading the amp with signal and overheating something. last time it happened it took it out of the case plugged it in and touched the chassis signal came on. weird

Nate

Subject: Re: K100c-7 intermittent signal
Posted by [steven](#) on Mon, 02 Oct 2017 09:53:38 GMT
[View Forum Message](#) <> [Reply to Message](#)

Once again a question, are both channels cutting out?
