

---

Subject: K150-8 noise issues

Posted by [NLKustom](#) on Tue, 05 Apr 2022 02:38:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hey guys, so I am new to this K150-8SC Plexi Combo.

Here are my questions/ concerns.

1) When you turn main power on, with nothing plugged in to it or no volume up , you can hear a power hiss, sorta low frequency. Is this normal?

2) When you rotate the reverb on you get a hum. The reverb seems to be working but the hum is too annoying to leave it on.

The only thing I've changed is the two prong power chord to a three prong chord. Followed the directions on here, removed the orange drop capacitor and re-soldered the wires. I had the reverb tank unplugged and removed to change the power chord, everything looked ok.

Any help before I take it to the shop for servicing?

---

---

Subject: Re: K150-8 noise issues

Posted by [NLKustom](#) on Tue, 05 Apr 2022 22:03:55 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

If this is in the wrong section, you can move it to the repairing section.

---

---

Subject: Re: K150-8 noise issues

Posted by [stevem](#) on Wed, 06 Apr 2022 14:05:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I am moving this to the repair section.

---